

ShopBot Control Software QUICK REFERENCE GUIDE -- OpenSBP® COMMAND Language

The Easy Language of CNC and Digital Fabrication

File Category Commands		Settings Category Commands	
File: execute Part File	FP [/Nm, {pX,pY,pZ,Rp,Ofst, plnge, Tb, z0, pA, pB}]	Mostly toggles Settings without parameters	
File: Edit	FE [/Nm]	Set to Absolute Distances	SA
File: New blank Part File	FN	Set to Relative Distances	SR
File: Goto/Single Step	FG [/Nm, {pX, pY, pZ, Rp, Ofst, plnge, Tb, z0}]	Set to PREVIEW Mode	SP
File: Conversion	FC [/Nm]	Set to MOVE/CUT Mode	SM
File: Set drive/directory	FS [Path, mask]	Set to Keyboard Arrow Control	SK (shortcut = 'K')
Move Category Commands		Values Category Commands	
Set Mode to Absolute Distance (SA) or Relative Distance (SR)		Values for Cutter, etc	VC [CutterDia, kX, kY, sfZ, dirZplng, pk%, sfA]
Move X axis	MX [new-X]	Values for Preview Screen	VP [grid, tbX, tabY, tbZ, sim, rot, center, show jog, rnd]
Move Y axis	MY [new-Y]	Variable Define	VV [Name, Value]
Move Z axis	MZ [new-Z]	Values of Speeds	VS [mvXY, mvZ, mvA, mvB, jXY, jZ, jA, jB]
Move 2 axis	M2 [new-X, new-Y]	Values of Ramp	VR [mrXY, mrZ, mrA, mrB, jrXY, jrZ, jrA, jrB]
Move 3 axis	M3 [new-X, new-Y, new-Z]	Values for taBbing	VB [dist pull-up, dist next, size, dist leads, 1-ON 0-Off, #]
Move Home	MH (Move to 0, 0 in X, Y; with Safe-Z pull-up if enabled)	Values of locAtion	VA [NEW value for locX, locY, locZ, locA, locB, NEW value for baseX, baseY, baseZ, baseA, baseB]
Move Acc axis	MA [new-Acc value]	Values for Units	VU [unX, unY, unZ, unA, CirRes, sCyX, sCyY, SmCir, unB]
Move B Axis	MB [new-B]	Values for Display	VD [prmpnts, #axes, units, unitsA, unitsB, consl, com, /Dist, remote, wr part log, wr sys log]
Move Distance at Angle	MD [Distance to move, angle, Z move]	Values for table Limits	VL [loX, hiX, loY, hiY, loZ, hiZ, loA, hiA, 0-OFF 1-ON, lob, hiB]
Move 4 Axis	M4 [new-X, new-Y, new-Z, new-A]	Values Input addresses (Change Axis address)	VI [com#, chn1, chn2, chn3, chn4, chn5, spd]
Move 5 Axis	M5 [new-X, new-Y, new-Z, new-A, new-B]	Values iNput switch mode	VN [limOn, Stop Switch type, torch/laser, extensive switch function settings tables]
Motors OFF	MO or M0	Value Height Control	VH [Settings for plasma cutter or laser cutter]
Move Speeds	MS [X,Y-Move-Speed, Z-Move-Speed (see also [VS])]	Values temp Offset	VO [For temporary offsets within files]
Jog Category Commands		Record Category Commands	
Set Mode to Absolute Distance (SA) or Relative Distance (SR)		Record Replay	RR [/#CommandsBack /blank=I] [A=ALL], #Reps
Jog X axis	JX [new-X]	Replay All	RP
Jog Y axis	JY [new-Y]	Record Save & edit	RS [/Filename, #CommandsBack /blank=ALL]
Jog Z axis	JZ [new-Z]	Record Activate	RA
Jog 2 axes	J2 [new-X, new-Y]	Record Inactivate	RI
Jog 3 axes	J3 [new-X, new-Y, new-Z]	Reset Record	RZ
Jog Home	JH (Jog to 0, 0 in X, Y; with Safe-Z pull-up if enabled)	Utility Category Commands	
Jog Acc axis	JA [new-Acc value]	Utility: Name Editor	UN [/Path & filename [default=EDIT] (Notepad OK)]
Jog B Axis	JB [new-B]	Utility: calcUlator	UU
Jog 4 Axis	J4 [new-X, new-Y, new-Z, new-A]	Utility: List Variables	UL [(list can be edited and/or saved)]
Jog 5 Axis	J5 [new-X, new-Y, new-Z, new-A, new-B]	Utility: display Values & settings	UV
Jog Speeds	JS [X-Jog-Speed, Z-Jog-Speed (see also [VS])]	Utility: Reset Defaults	UR [/A=All values including calibration and location]
Cut Category Commands		Utility: Save current config	US
CUTS Outside, Inside, or True; See: Cutter Diameter with [VC]		Utility: Diagnostic display	UD (UV and UD are automatically saved in PROBLEM.LOG)
Cut Circle	CC [Dia, {O-I-T, Dir, B<, E<, Plunge, Rep, pX, pY, [/1-Tab 2-Pckt 3-Spr 4-SprBp], 1-no pullup, 1-plgfrom0}]	Utility: Install Firmware	UI [Install Control Box Firmware]
Center Point Circle	CP [Dia {x,y, O-I-T, Dir, B<, E<, Plunge, Rep, pX, pY, [/1-Tab 2-Pckt 3-Spr 4-SprBp], 1-no pullup, 1-plgfrom0}]	Utility: Zero	UZ [Zero all axes and Table Base Coordinate System]
Cut quick Arch	CA [Width,Height,{O-I-T, Dir, Alignmnt<, Plng, Rep, pX, pY, 1-Tab, 1-no pull-up, 1-plgfrom0}]	Virtual Tools	
Cut G-code Circle	CG [Dia, endX, endY, Xcent, Ycent, {O-I-T, Dir, Plg, Rep, pX, pY, [/1-Tab 2-Pckt 3-Spr 4-SprBp], 1-no-up, 1-plgfrm0}]	Part Wizard	TP [Launch Part Wizard from ShopBot Control Software]
Cut Rectangle	CR [LengthX, {LengthY, O-I-T, Dr, Strt, Plg, Rp, [/1-Tab 2-Pckt], 1-plunge from 0}]	TypeSetter	TT [V-Carve Fonts on your computer]
Custom Cut Setup	CS	Copy Machine	TC [Use with Digiizing Probe to copy existing models]
Zero Category Commands		Drill Press	TD [Create routines for drilling holes]
Careful! No Parameters Required. Zeroing Happens on 2 nd Letter of Command		Header Writer	TH [Insert notes about bits, zeroing locations, etc to .sbp files]
Zero X axis	ZX		
Zero Y axis	ZY		
Zero Z axis	ZZ		
Zero Acc Axis	ZA		
Zero B Axis	ZB		
Zero X & Y (2D)	Z2		
Zero X, Y, & Z (3D)	Z3		
Zero All 4 Axes	Z4		
Zero All 5 Axes	Z5		
Zero Table Base Coordinates	ZT (Resets Location in terms of Base Values)		

Comment [ST1]: For some reason, this row needs to be here to convert to PDF properly – nb Jul08